

# Gertbot

## Rev 1.0, 8 September 2014

The Gertbot is a motor/power controller board for the Raspberry-Pi. The strength of the board is that it has its own CPU which frees up the Raspberry-Pi from a lot of intense computations and will take care of all the real time requirements. All you have to do is give it high level commands. Like: Board 2, Motor 1, take 2432 steps at 67 Hz. Even giving those commands is done for you using the free GUI which comes with it!

Hardware features:

- Four H-bridges 8V-30V, 2.5A.
- Bridges can be re-configured for 2x 5A or 1x 10A.
- Two open drain outputs 30V, 3A.
- Power full 64MHZ ARM Cortex-M3 processor
- RS232 connects direct to the Raspberry-Pi or other serial interface.
- Cascade port to control up to four boards at a time.
- 20-pin connector programmable for:
  - Automatic motor end-stop
  - Four 12-Bit ADC ports
  - Two 12-bit DAC ports
  - 8-16 general purpose I/O

Software controllable features:

- Brushed<sup>1</sup> motors:
  - Control direction
  - Speed control PWM 10Hz-10KHz, 0-100%.
  - Soft start 0.1sec .. 5 seconds prevents in-rush current
  - Stop on switch hit.
- Stepper motors:
  - Take X-steps in either direction
  - Step speed 0.06 Hz .. 5KHz.
  - Stop on switch hit.
- Short-circuit or high temperature error detection
- On error, keep running, stop motor, stop board or stop all boards
- I/O pins programmable functions
- Emergency stop, halts whole system.

A lot of effort has gone into the software. The board comes with drivers, example code and a GUI all complete with source code. Depending how fast you can screw the wires down, you can have your motors running in a few minutes!

The board can also be used to drive other power electronics like LEDS, relays etc. Using a 30V supply and 2mA LEDS you can drive three sets, each of ~12500 RGB LEDS, using the boards PWM feature to control the colour.

---

<sup>1</sup> I used the term 'brushed motor' to indicate the standard DC brushed motors. You find those in most toys.

<b>READ THE MANUAL!</b>
-------------------------

The most difficult part of controlling motors has been taken care of by the software running on the Gertbot. Instead of directly having to manipulate the motors, you send high-level commands to the Gertbot which will execute them. But this does mean that you have to learn what those commands are. Therefore you should read the manual.

**Quick start:**

For those of you who want to start quickly: there is a Gertbot GUI which you can use to control every feature of the Gertbot. There is a separate Gertbot GUI manual which guides you through the controls but it refers to this manual to explain the details of operation.

**Advanced:**

The Gertbot Advanced guide helps you with cascading boards, operate bridges in parallel to double or quadruple the maximum current. It also tells you how to upload new software versions or how erase the current program and put your own software on the board.

## Contents

0	I want to use it NOW!.....	5
1	Overview:.....	9
2	Connecting things up .....	9
2.1	Connecting motors.....	9
2.2	Connecting stepper motors.....	11
2.3	Connecting motor power.....	11
2.4	Connecting end-stops.....	12
2.5	Connecting Open drain output .....	13
2.6	Connecting to other than Raspberry-Pi.....	14
2.6.1	Connect to J12 (cascade connector).....	14
2.6.2	Connect to J6 (Pi connector).....	15
2.6.3	Connect to J14 (Not mounted).....	15
3	Commands.....	16
3.1	Identifier.....	16
3.2	Values .....	17
3.3	Making commands.....	17
3.4	Command table .....	18
4	Command details .....	18
4.1	Read version.....	18
4.2	Operation mode.....	19
4.3	End-stop set up.....	20
4.4	DC/Brushed Pulse Width Modulation Motor Frequency.....	21
4.5	Brushed Motor Duty Cycle .....	22
4.6	Start/stop Brushed Motor .....	22
4.7	Read error status .....	23
4.8	Stepper motor take steps .....	23
4.9	Stepper Motor Step Frequency .....	24
4.10	Stop all .....	25
4.11	Switch open drain .....	25
4.12	Set DAC.....	26
4.13	Read ADC.....	26
4.14	Read I/O.....	26
4.15	Write I/O.....	27
4.16	Set I/O.....	27
4.17	Set ADC/DAC .....	28
4.18	Board configure .....	28
4.18.1	Board Synchronous command mode. ....	28
4.18.2	'Attention' signal mode.....	29
4.18.3	Stop on error. ....	29
4.18.4	Board configure command overview.....	29
4.19	Read board status .....	30
4.20	Clear errors??.....	31
4.21	Read motor status.....	31

5	Operating details .....	32
5.1	End-stops.....	32
5.2	Halt.....	33
5.3	Frequency settings .....	33
5.3.1	Jitter.....	33
5.3.2	Accuracy. ....	34
5.4	Synchronous operation.....	34
5.4.1	Direct commands. ....	34
5.4.2	Synchronous commands .....	36
6	Motor error.....	37
6.1	Reaction to an error.....	37
6.2	Oscillation.....	38
6.3	Soft start / Inrush current .....	38
7	Appendix A: error codes.....	40
8	Appendix B: Technology.....	41
8.1	DC voltage.....	41
8.2	AC voltage.....	41
8.3	H-bridge.....	42
8.4	DC Brushed motor.....	43
8.5	Stepper motor.....	44
8.5.1	Connections.....	44
8.5.2	Mechanics .....	45
8.5.3	Rotor hold.....	45
8.6	Inductors.....	46
8.6.1	Switching it on.....	46
8.6.2	Switching it off.....	47
9	Appendix C: asc2bin.....	48
10	Appendix D: software.....	49

## 0 I want to use it NOW!


If you are like a lot of engineers you don't want to read a manual, you want to get started NOW. I can't recommend that but this chapter might limit the damage if you still want to do so. Please use the following steps:

1. Connect a DC-brushed motor or stepper motor to the Gertbot. Also connect a power supply for your motors to the Gertbot. See §2 *Connecting things up* for how to do that.  
(From here the instructions assumes you have connected a DC motor to contacts A1,A2 or a stepper motor to contacts A1,A2,B1,B2)
2. Plug the Gertbot board on top of a Raspberry-Pi board which is powered down. Then boot the device.  
(On a B+ make sure to plug the board on GPIO pins 1-26.)
3. Login and download the software: `git clone git://github.com/<TODO>`  
(You might want to make a directory to put all the Gertbot data into)
4. If you have not started the X-windows system yet, do so now: `startx`
5. Open a terminal window and go to the directory where you have cloned the Gertbot GUI software. Type `./gertbot` (That is dot-slash-gertbot). (You may get a warning that your UART is not available. If so follow the instructions to enable the UART.) After that you see this:



(The "Com.." is only present if you run the gui under windows)


- 6. Press the **Connect** button. A log window will pop-up and show the search for boards. Default from the factory the board has ID 0 so you should see this:




- 7. Use the control under “**Motor 0**” to select the operating mode.

For a DC brushed motor select: **DC/brushed**

For a stepper motor select: **Step Gray**:




8. For DC/brushed motors you see this:



You can now play with the  buttons and your motor should run.

If you have a big motor the over-current protection might kick in. (This can be so fast so you will not notice it. All you find is that your motor does not start). If so set the Ramp to 1 second:  
(See §6.3 *Soft start / Inrush current* for details about that)



9. For stepper motors you see this:



You can now play with the  buttons and your motor should take 10 steps.


In the beginning I would advise you to stop with no power on the stator. Use the  button to do that.

For more information about the Gertbot Gui read the manual: Gertbotgui.pdf

## 1 Overview:

The boards consist of:

- A Central Processing Unit (CPU)
- Four H-bridges each 2.5A
- Two open drain outputs
- Two Digital-to-Analog converters (in CPU)
- Four Analog-to-Digital converters (in CPU)
- 10 general purpose input/output ports
- A UART connection
- A cascade port



The four H-bridges can be used to control either four brushed motors or two stepper motors or two brushed and one stepper motor. You talk to the board using the UART (serial port) which must be set to 57600 baud, 8 bits 1 start, 1 stop bit, no parity.

The Gertbot is controlled by sending commands over the UART port. There are commands to select what type of motors you have (brushed or stepper or a mixture). There are commands to run your motors, to specify when they should stop, to control the relays, read the ADC, set the DAC and a lot more.


There is an expansion connector which allows you to connect up to four Gertbot boards in parallel. This gives you control over maximum 8 stepper motors or 16 brushed motors or various mixtures of both.

## 2 Connecting things up

### 2.1 Connecting motors.


The contacts for the motors are identified on the board using the notion A1, A2, B1, B2, C1, C2, D1, D2. A motor coil is always connected between X1 and X2. Thus between A1 and A2, B1 and B2 etc.

Looking at the top of the board you get these connections:




Gertbot **Top view.**

In order to connect motors and power supplies use the following diagram:




Gertbot **Top view. DC/brushed motors**



Gertbot **Top view. Stepper motors**

Notice that there is only one ground (blue) but the top outputs and the bottom outputs can have a different power supply.

If you ever forget and don't have this manual available: At the **bottom of the board** you find a diagram which shows where to connect the motor coils and the power supplies.



Gertbot **BOTTOM VIEW**.

## 2.2 Connecting stepper motors.

Brushed motors have a high impedance and you can connect a brushed motor direct to the board. This is not the case with a lot of stepper motors!

**Beware!**  
**Some stepper motors may need series resistors to connect them to the board.**

The controller needs a minimum of 8V to work. If your stepper motor requires less voltage you must add series resistor.

If you connect up a stepper motor you will need to use a pair of connections. Thus a stepper motor connects to A1 & A2 and B1 & B2. Most likely your stepper motors has four or six wires. For details about stepper motors see chapter 8.5 *Stepper motor*.

## 2.3 Connecting motor power

For a motor to run you must connect an external power supply. The motor controllers should be connected to a power source between 8 and 18Volt.

**For safe operation do not connect more than 18volts!!**

The board can withstand operating voltages up to 30V but anything above 18V can cause dangerous voltage levels to appear on the motor output pins.

The bridge controllers need a minimum of 8V. If the input voltage is below 8V the controller will refuse to work. The power is connect with the plus to pin VAB or VCD. The ground goes to the Gnd

connections. You can use a different voltage for VAB as for VCD, but all grounds of the board are connected together.


Again at the bottom of the board you find a diagram which shows the power connections connected to a battery symbol.

If you have a motor for a voltage less than 8volts you can try to connect it using a series power resistor. This will work for stepper as well as brushed motors.

## 2.4 Connecting end-stops.

To connect end-stops you have to add a contact between one of the EXT pins and ground. You can use a mechanical switch or an optical switch. As each EXT pins has a pull-up resistor of 4700 Ohms to the controller's 3.3 volt supply you only need to connect a switch between the pin and ground.

These are the J3 pins which can be programmed as end-stop:




Gertbot end-stop pins.

Looking at the pins above the end-stops are assigned as follows:

Motor 3:B	Motor 2:B	Motor 1:B	Motor 0:B
Motor 3:A	Motor 2:A	Motor 1:A	Motor 0:A

As stated all you need is a switch from the pin to ground. The following diagram shows how to connect all four B end-stop switches:



You can connect a switch which is normally open and gets closed if the end-stop position is reached. In that case you must program the end-stop as active low.

Alternative you can connect a switch which is normally closed and gets opened if the end-stop position is reached. In that case you must program the end-stop as active high. This is the preferred way of connecting an end-stop.


If you use end-stops you **MUST** make sure your motor's rotational direction is correct. The simplest way is to use the GUI and use the button of the GUI to make the motor move into the direction of end-stop A. If the motor goes into the opposite direction swap your motor wires around or swap your end-stop wires around. Also test your end-stop. There are two ways to do this:

1. Set the motor moving, operate the end-stop and check that the motor stops.
2. Operate the end-stop and check that the motor refuses to start in that direction

If it does not work blame your circuit, not the Gertbot as that has been thoroughly tested! Did you connect to the right 'ext' pin?

## 2.5 Connecting Open drain output

The Gertbot has two open drain ports. The switch element is an NMOSFET. Each can switch 30V 3A. The following picture shows the open drain connections:



Gertbot open drain connections.

For those who are no familiar with open drain connections: An open drain is like a switch. But you can only switch DC currents and you must connect the plus to the drain pin (because the switch is an NMOSFET).



As you can see from the diagram there is no power available at the output. For an open drain output to work, the user must provide an external power source. The open drain output does nothing more than provide a path with a very low resistance to ground when it is switched on.

There is no protection on the open drain outputs. So the board will get damaged if you exceed the current or voltage specification. MOSFETS have the notorious habit of a large capacitive coupling from the drain to the gate. To prevent capacitive voltage spikes from blowing up the controller there is RC

filtering between the gate and the controller. However there is no guarantee that it will protect under all circumstances.

## 2.6 Connecting to other than Raspberry-Pi

The Gertbot board takes its commands in the format of a serial UART stream. (UART stands for Universal Aynchronous Receive Transmit). Beware of the difference between a UART stream and a RS232 stream. The UART stream is a protocol. RS232 is a physical interface standard. ***Do not connect the board to an RS232 port. RS232 has a voltage swing between +/- 3V and +/- 15Volts. It will damage the board.***

The requirements to connect a serial port to the Gertbot are:

- Amplitude 3.3 Volts
- 57600 baud
- 8 data bits
- 1 start bit
- 1 stop bit
- No parity

Thus any equipment which can read and write a serial UART stream can be used to control the boards. The board does not use flow control. There are three ways to connect a serial cable.


### 2.6.1 Connect to J12 (cascade connector)

This is the easiest way but prevents you from using more than one board. You will need an 8 pin female header organised as two rows of 4 pins 0.1" pin pitch. Connect the signals as follows:

Signal	Pin	Pin type on Gertbot
Ground	1	Ground
5Volt ~65mA	3	Power
Transmit	6	Input
Receive	4	Output
Attention (Optional)	5	Output

Transmit is the transmit pin of your external computer. It is a receive pin of the Gertbot.  
Receive is the receive pin of your external computer. It is a transmit pin of the Gertbot.

Below is a picture of a FTDI USB to TTL cable connected to J12. The 5V output of the cable can power the Gertbot so no external 5V supply is required.



### 2.6.2 Connect to J6 (Pi connector)

You will need minimal a 10 pin male header organised as two rows of 5 pins 0.1" pin pitch. (Maximum you can use a 26 pin male header organised as two rows of 13 pins 0.1" pin pitch) Connect the signals as follows:

Signal	Pin	Pin type on Gertbot
Ground	6	Ground
5Volt ~65mA	2 and/or 4	Power
Transmit	8	Input
Receive	10	Output
Attention (Optional)	22	Output

Transmit is the transmit pin of your external computer. It is a receive pin of the Gertbot.

Receive is the receive pin of your external computer. It is a transmit pin of the Gertbot.

(Not picture is available of this)


### 2.6.3 Connect to J14 (Not mounted)

For this you will need to solder a connector on the Gertbot. You will need a 5 pin male header organised as one row of 5 pins 0.1" pin pitch. Connect the signals as follows:

Signal	Pin	Pin type on Gertbot
5Volt ~65mA	1	Power
Ground	2	Ground
Transmit	3	Input
Receive	4	Output
Attention (Optional)	5	Output

Transmit is the transmit pin of your external computer. It is a receive pin of the Gertbot.  
 Receive is the receive pin of your external computer. It is a transmit pin of the Gertbot.

Below is a picture of a FTDI USB to TTL cable connected to J14. The 5V output of the cable can power the Gertbot so no external 5V supply is required.



### 3 Commands.

All commands are 8 bit bytes and are in **binary** format, *not ASCII*, so you cannot type these values into a terminal program. Each command must be preceded by the value 0xA0 and closed with the value 0x50. Alternative you can make a file with commands and then send that file to the UART port e.g.:

```
cp start_all_engines.bin > /dev/ttyAMA0
```

The Gertbot comes with several support programs one of which is a GUI which lets you control your Gertbot boards using only your mouse and allows you to make commands files as mentioned above.

#### 3.1 Identifier

You can control multiple boards each with up to four motors. Therefore most commands have an identifier (ID) byte which tells for which board and for which motor on that board the command is intended. As you can cascade a maximum of four boards each with maximum four motors that gives you 4x4=16 potential motors to control. Therefore the ID byte can range from 0 to 15. The ID's 0-3 are for the first board, 4-7 for the second etc. The H-bridge outputs are identified on the board using the notion A1, A2, B1, B2, C1, C2, D1, D2. See § 2 *Connecting things up* on how to connect your motor to those. The following table specifies the relation between the ID and the connections (motors) it controls.

ID	Board	Connections	ID	Board	Connections
0	0	A1-A2	8	2	A1-A2
1	0	B1-B2	9	2	B1-B2
2	0	C1-C2	10	2	C1-C2
3	0	D1-D2	11	2	D1-D2

4	1	A1-A2	12	3	A1-A2
5	1	B1-B2	13	3	B1-B2
6	1	C1-C2	14	3	C1-C2
7	1	D1-D2	15	3	D1-D2

If you are operating stepper motors you need two pair of connections for one stepper motor. Thus the four connections A1, A2, B1 and B2 together control *one* stepper motor. The same holds for the set of C1, C2, D1 and D2 which together control *another* stepper motor. As all of those MUST work in unison, a stepper motor id can only be even: 0,2,4,6,8,10,12. Thus sending a command to id 0 will control all four of the outputs A1, A2, B1, B2. Stepper motor commands send to an odd ID will be ignored and raise an error.

Some commands are not designated for a motor but for the board itself. In that case the ID value 0,1,2,3 are all treated as for the first board, ID values 4-7 address second board etc.

### 3.2 Values

Many commands take one or more parameters. As mentioned before all data is send in binary format. Thus a value of 76 (decimal) is send as 0x4C (0x mean the number is in hexadecimal format). Sometimes values are too big to fit in a single byte and instead two or three bytes must be used. In all cases the most significant (MS) value is in the first byte. Thus the least significant (LS) value is in the last byte. This is the case for transmitted as well as received data. For example to send the value 27616 you have to first translate this to hex: 0x6BE0 and then send it as two bytes: 0x6B followed by the byte 0xE0. If you have to send a big number e.g. 4705118 you send three bytes: 0x47 0xCB 0x5E. There is one command which takes signed number: the step command. In that case you must make sure your three bytes are accordingly signed (twos complement format<sup>2</sup>). See also the examples here: § 4.8 *Stepper motor take steps*.

### 3.3 Making commands

The commands seem complex and making an error in them is easily done. The Gertbot Gui is an alternative of making commands with little effort. So easy that these days I rarely refer to the command manual. Instead I give the command using the Gui and then copy the hex values from the log window in my program. (But I still needed the text below to put the correct code in the Gui).

---

<sup>2</sup> Explanation of twos complement is outside the scope of this manual. Please read up on that.

### 3.4 Command table

Command	Val		Parameters
Operation mode	0x01	id	0:off,1:brushed,2:stepper gray,3 stepper pulse
End-stop setup	0x02	id	Bits 0,1 enable Bits 2,3 polarity
Board status	0x03	ID	Return status of board
DC motor Frequency	0x04	id	2 byte value. Range 10-30K
DC motor duty Cycle	0x05	id	2 byte value. Range 0-1024 for 0-100%
Start brushed motor	0x06	id	0: Stop, 1: goto A, 2: goto B
Read error status	0x07	ID	- (Returns 0x07, id, 2 byte error code)
Stepper motor take steps	0x08	id	3 byte signed value. 0 stops.
Step Freq.	0x09	id	3 byte value. Range 16-128000
Stop all	0x0A	0x81	Stops all motors on all boards
Open Drain	0x0B	id <sup>1</sup>	0:idle, 1:active,
Set DAC	0x0C	id <sup>1</sup>	2 byte value
Read ADC	0x0D	id	- (Returns 0x0D,id, 2 byte error code)
Read I/O	0x0E	ID	3 bytes
Write I/O	0x0F	ID	3 bytes
Set I/O	0x10	ID	3 bytes
Set ADC/DAC	0x11	ID	ADC byte DAC byte
Configure	0x12	ID	3 bytes
Read board version	0x13	ID	(Returns 0x13,id, 2 byte version)
Motor status	0x14	ID	Return 16 status bytes
Execute Sync.	0x15	0x18	Run all synchronised commands
Board status			

For more information see the next chapter: *Command details*.

id<sup>1</sup>: id can be 0,1,4,5,8,9,12,13 only.

ID: Board id, least significant two id bits are ignored.

## 4 Command details

This chapter lists each command, the command format the parameters and often examples.

Each command that generates a response from the Gertbot (The Gertbot send back a number of reply bytes) has to send multiple closing bytes (Value 0x50). To be precise, if a command returns X bytes the command must be followed by X times the 0x50 value.

Throughout this document you will find references to 'Direction A' or 'Direction B'. I use the terms A and B as the real physical direction depends on how the motor wires are connected. e.g. for a brushed motor the direction inverts when the two wires are swapped.

### 4.1 Read version

0xA0 0x13 <ID> 0x50 0x50 0x50 0x50

This command returns the version of the board indicated with ID.

ID can be in the range 0-15 but the LS two bits are ignored.

This command will return 4 bytes.

The first byte is the original ID.

The second is 0x13

Bytes three and four are the MS & LS values of the version code.

*As the command returns 4 bytes it must be followed by at least 4 bytes of 0x50.*

## 4.2 Operation mode

0xA0 0x01 <id> <mode> 0x50

This command sets the operation mode of a motor. The id can be in the range 0-15 for brushed motors.

The id must be even for stepper motors. If you set a motor up as stepper motor, the following motor (with id+1) is disabled. Thus if you set motor 0 to stepper mode you can no longer send commands to motor 1. You can NOT set motor 1 to stepper mode.

There are currently four operating modes:

- 0 : Switch motor <id> off
  - 1: Motor <id> is setup as stepper motor using Gray code. The <id+1> is no longer usable.
  - 2: Motor <id> is setup as stepper motor using Pulse code. The <id+1> is no longer usable.
  - 8 : Motor <id> is operating in brushed mode
- All other values are illegal.

If a motor pair is set up as stepper motors all command for the pair must go to the lowest id. There are two stepper motor modes, each has a different waveform.

After sending a mode to a motor you must specify a frequency before the motor can be used, (even if the motor was already in that same mode.)

### Mode 1.

Stepper motor mode 1 uses gray coded outputs:




Figure a: Mode 1, gray waveform: positive steps.




Figure b: Mode 1, gray waveform: negative steps.

**Mode 2.**

Stepper motor mode 2 uses pulse coded outputs:




Figure c: Mode 2, pulse waveform: positive steps.





Figure d: Mode 2, pulse waveform: negative steps.

**Mode 3-7 are not yet used.**

Mode 3 is reserved for wave-output:

**Mode 8.**

Mode 8 is for DC/brushed motors. In brushed mode the board supports Pulse Width Modulation (PWM) to control to motor speed. For details about PWM see § 4.4 *DC/Brushed Pulse Width Modulation Motor Frequency* and 4.5 *Brushed Motor Duty Cycle*.

**4.3 End-stop set up**

0xA0 0x02 <id> <end-stop mode> 0x50

This command enables or disables the end-stop mode of a motor and sets the end-stop polarity. Bits 0,1 enable/disable each of the two end-stops. Bits 2,3 set the end-stop polarity. For more details about end-stops see chapter 5.1 *End-stop*.

Bits 1,0	End-stop mode
0	Both off
1	A is on B is off
2	A is off B is on
3	A and B are on

End-stop enable bits

Bits 3,2	End-stop mode
0	Both active low
1	A active high B is active low
2	A active low B is active high
3	Both active high

End-stop polarity bits

- Active high mean the motor is stopped if the end-stop input is high.
- Active low mean the motor is stopped if the end-stop input is low.

The enable and polarity bits are send combined in the LS 4 bits of the command. The MS bits are reserved for future use.

Example : On board 0 motor 2, set both end-stops active low: 0xA0 0x02 0x02 0x03 0x50.

End stops are very useful to implement basic motor control. e.g. to open a garage door you would activate an end-stop switch when the door is full opened and a second switch when it is fully closed. Next you only have to send the command to start the motor in a certain direction. You do not have to send a stop command at the right time as the Gertbot itself will stop the motor when the end-stop switch is activated.

#### 4.4 DC/Brushed Pulse Width Modulation Motor Frequency

0xA0 0x04 <id> <MS ><LS> 0x50

Pulse Width modulation (PWM) is a technique used to control the speed of brushed motors. Instead of lowering the voltage, the motor controller provides power for a short period of time and then removes the power. Because of the inherence slow mechanical response of the motor it will run slower. In fact the mechanical behavior is better than with a lower voltage as the torque of a 10% PWM driven motor is higher than from a motor with only 10% of its voltage applied.

This command sets the PWM frequency used in brushed mode. The PWM causes pulsed signals to arrive at your motor. The coil in your motor is an inductor and pulses with an inductor can cause havoc if you don't know what you are doing. (see also § 8.6 *Inductors*.) Working with pulses and an inductor can cause very high voltage. Although the H-bridges are somewhat protected, they cannot withstand infinite voltages. So always be careful when using PWM. If you set the duty cycle to 100% there are no pulses an you can reasonably safely connect a DC motor.




The frequency must be between 10Hz and 30 KHz. If you change the brushed frequency the program will set the corresponding duty cycle for you. You can change the duty cycle whilst the motor is running.

*Do not use a low frequency with big DC-brushed motors as it will cause extreme high inrush currents and that is likely to trip the over current protection. It will also make the controllers very hot especially if you disable the high current trip. See also §6.3 Soft start / Inrush current*

#### 4.5 Brushed Motor Duty Cycle

0xA0 0x05 <id> <MS><LS> 0x50

This command sets the Pulse Width modulation (PWM) duty cycle used in brushed mode. The value must be between 0 and 1000. The duty cycle is specified in step of 1/1000 of 100%. Thus 100 is 100%, 500 is 50% etc. Setting a duty cycle of 100% (0x0A 0x05 <id> 0x03 0xE8 0x50) gives a signal which is constantly high (DC output) on the motor pins<sup>3</sup>.



The duty cycle is time-A divided by time-B. The picture above shows a duty cycle of 25%. (0x0A 0x05 <id> 0x00 0xFA 0x50). The duty cycle is maintained even if you change the frequency.

Default (after enabling) the duty-cycle for a brushed motor is set 100% by the system.

Unfortunately the hardware does not allow the duty cycle and the frequency to be independently set. Thus the Gertbot updates the duty cycle after a frequency change. As a consequence the duty cycle can be off the requested value for a few micro seconds after changing the frequency. There is currently no way around this.

#### 4.6 Start/stop Brushed Motor

0xA0 0x06 <id> <mode> 0x50

This command starts a brushed motor in either direction or stops it. You can start a brushed motor only if:

- You have set the mode to brushed
- You have set a frequency.
- The HALT line is not active
- You have no end-stops enabled or the end-stop in the direction you are moving is enabled but not active.
- You have correctly connected power and a brushed motor.

The direction (or stop) is set by the LS 4 bits of the command. Of the sixteen possible values three are used:

0x0 : Stop the motor

0x1 : Run in the A direction

0x2 : Run in the B direction

The other values are reserved for future use.

<sup>3</sup> Unless you start rapidly switching your motors on/off or forward/backwards.

To make the motor go into a specific direction one output is set high and the other remains low. The following table shows the power on the motor control pins in relation to Run-A and Run-B:

Mode		A1, B1, C1, D1	A2, B2, C2, D2
0x0	Off	Low (Gnd)	Low (Gnd)
0x1	Run A	High (V motor)	Low (Gnd)
0x2	Run B	Low (Gnd)	High (V motor)

### Soft start.

To prevent large in-rush currents the Gertbot supports soft-starting. For details about soft-starting see § 6.3 *Soft start*. There are sixteen soft start (ramp-up) values. The following table shows the soft-start value and the start-up time in seconds.

Code	Time	Code	Time	Code	Time	Code	Time
0x0	Off	0x4	0.375	0x8	2.5	0xC	2.5
0x1	0.05	0x5	0.5	0x9	1.5	0xD	3
0x2	0.125	0x6	0.75	0xA	1.75	0xE	4
0x3	0.25	0x7	1	0xB	2	0xF	5

Soft start time in seconds.

To start multiple motors at the same time use the 'sync' command system. See 4.18.1 *Board Synchronous command mode*.

The 'linear' stop command is an exception in that it is also used to stop stepper motors. See also 4.8 *Stepper motor take steps*.

Example start command:

0xA0 0x06 0x01 0x71 0x50 : Start board 0 motor 1 in direction A, ramp-up in 1 second.

### 4.7 Read error status

0xA0 0x04 <id> <MS ><LS> 0x50 0x50 0x50 0x50

The system keeps track of the last 16 errors. This command will return the status of the most recent error. If there are no (more) errors the return value will be 0. This command will return 4 bytes.

The first byte is the original ID.

The second byte is 0x06

Bytes three and four are the MS & LS value of the error code.

See appendix A for a full list of error codes.

***As the command returns 4 bytes it must be followed by at least 4 bytes of 0x50.***

### 4.8 Stepper motor take steps

0xA0 0x08 <id> <MS ><MM><LS> 0x50

This command specifies how many steps a stepper motor should take. The value from the three bytes is a signed value between -8388607 and 8388607. A positive value moves the motor in direction A, a negative value towards B. You can start a stepper motor only if:

- You have set the mode to one of the stepping modes.
- You have set a frequency.
- The HALT line is not active

- You have no end-stops enabled or the end-stop in the direction you are moving is enabled but not active.
- You have correctly connected power and a stepper motor.

Once the number of steps have been taken the motor will stop but the current (power) will remain on the motor windings, holding the rotor anchored through the magnetic force. A new 'take steps' command will replace a command in progress.

A value of 0 will stop the motor at the end of the next step but the current (power) will remain on the motor, holding the rotor anchored. There is a second way of stopping a stepper motor: using the **Stop brushed motor** command. The difference is that the power is removed from the stepper motor coil and thus the rotor will not be anchored. As a result the rotor may change position if there is enough external force applied to it. This will result in the loss of system integrity.

### Remaining steps.

When a stepper motor is stopped or when it receives a new command before it has finished the previous command, the system makes a copy of the remaining step counter. This value can be read by the user and can be useful in retaining the system integrity. The system has only one storage location for the number of remaining steps thus any new step will cause the loss of the previous value. The user can send multiple stop commands as the "remaining steps value" is not overwritten when the system is already halted.

If the 'attention' line is set to indicate 'steps-done' it will go low as soon as the step command is started. It will go high again when all stepper motors are done.

To start multiple motors at the same time use the 'sync' command system. See *4.18.1 Board Synchronous command mode*.

Some examples:

100 steps in direction A:

- A0 08 00 **00 00 64** 05 (Stepper motor on A1..B2)
- A0 08 02 **00 00 64** 05 (Stepper motor on C1..D2)  
(The bold part is the number of steps)

To step in the opposite direction use minus 100:

- A0 08 00 **FF FF 9C** 05
- A0 08 02 **FF FF 9C** 05

If you have given a large number of steps and want the system to stop send a step value of 0:

- A0 08 00 **00 00 00** 05 (Stop motor on A1..B2)
- A0 08 02 **00 00 00** 05 (Stop motor on C1..D2)

The motor will stop but the power will remain on the stator.

Or you can send a 'DC stop' command:

- 0xA0 0x06 0x00 0x00 0x50: Stop board 0 motor 0.

The motor will stop and the power will be removed from the stator.

Note: Even a motor running at the maximum stepper frequency of 5KHz will need ~28 minutes to take 8388607 steps.

## 4.9 Stepper Motor Step Frequency



0xA0 0x08 <id> <MS ><MM><LS> 0x50

This command specifies the step frequency. The minimum frequency is 1/16 Hz (1 step every 16 seconds). The maximum frequency is 5000 Hz. The value passed in the command, is the frequency you

want multiplied by 256. Thus the minimum value you should send is 0x000010, the maximum value is 0x138800.

It is not always possible to set the exact frequency but in all cases the real stepper frequency is better than 0.02% accurate.

The figures below show how the step frequency is related to the step waveforms.



Some examples:

10.5 Hz :  $10.5 * 256 = 2688 = 0x00\ 0x0A\ 0x80$

571.7 Hz :  $571.7 * 256 = 146355 = 0x02\ 0x3B\ 0xB3$

1500 Hz :  $1500 * 256 = 384000 = 0x05\ 0xDC\ 0x00$

For more details about setting or changing the frequency see § 5.3 *Frequency*.

#### 4.10 Stop all

0xA0 0x0A 0x0A 0x50

This command stops all motors on all boards. In contrast to an emergency stop all the stepper motors will remain powered.

#### 4.11 Switch open drain

0xA0 0x0B <id> <on/off> 0x50

This command activates or de-activates one of the open drain outputs on a board. As there are only two open drain per board the valid id values are 0,1,4,5,8,9,12,13. The on/off byte can be 0x00 (open drain off) or 0x01 (open drain on). Due to the nature of an open drain output *off* means **no current** and the open drain output is ***high***

#### 4.12 Set DAC

0xA0 0x0C <id> > <MS ><LS> 0x50

This command writes a value to the on-board DAC converter. As there are only two DACs per board the valid id values are 0,1,4,5,8,9,12,13. The current DAC is 12 bits Therefore the upper 4 bits of the 16-bit value are ignored.

**Warning:** the board uses the Digital-to-Analog converter inside the Atmel SAM32 chip. However these 12-bit DAC's do not have the full 3.3V voltage range. The range is from maximum ~2.75 volts to a minimum of ~0.66 volts.

#### 4.13 Read ADC

0xA0 0x0C <id> > <MS ><LS> 0x50 0x50 0x50 0x50

This command reads a value from the on-board ADC converter. The returned value is unsigned. As the current ADC is 12 bits the upper 4 bits of the return value are always zero. This command will return 4 bytes:

- The first byte is the original id.
- The second byte is 0x0C
- Bytes three and four are the MS & LS value of the ADC.

***As the command returns 4 bytes it must be followed by at least 4 bytes of 0x50.***

The ADC converter is operating in continuous conversion mode. This means it reads a new value every millisecond and the value is stored. The value returned will be the last store value which can be up to 1 millisecond old.

#### 4.14 Read I/O

0xA0 0x0E <id> 0x50 0x50 0x50 0x50 0x50

This command returns the status of all expansion pins. To allow space for future boards with more I/O the command has 3 bytes but the MS byte is currently unused and always returns 0x00.

MS byte bit	From	MM byte bit	From	LS byte bit	From
7	-	7	DAC1	7	EXT7
6	-	6	DAC0	6	EXT6
5	-	5	ADC3	5	EXT5
4	-	4	ADC2	4	EXT4
3	-	3	ADC1	3	EXT3
2	-	2	ADC0	2	EXT2
1	-	1	Spare1	1	EXT1
0	-	0	Spare0	0	EXT0

Read input byte association table

The command does NOT check which pins are enabled as input. It returns the raw data read. As such you get the status of special function pins as well. Note that the return status of an analog pin (ADC/DAC) is undefined. This command will return 5 bytes:

The first byte is the original id.

The second byte is 0x0E

Bytes three, four and five are the MS,MM & LS values read.

*As the command returns 5 bytes it must be followed by at least 5 bytes of 0x50.*

#### 4.15 Write I/O

0xA0 0x0F <id> <MS ><MM><LS> 0x50

This command sets the status of the user pins on the expansion connector. To allow space for future boards with more I/O the command has 3 bytes but the MS byte is currently unused. Write to pins which are NOT defined as output pins are ignored.

MS byte bit	To	MM byte bit	To	LS byte bit	To
7	-	7	DAC1	7	EXT7
6	-	6	DAC0	6	EXT6
5	-	5	ADC3	5	EXT5
4	-	4	ADC2	4	EXT4
3	-	3	ADC1	3	EXT3
2	-	2	ADC0	2	EXT2
1	-	1	Spare1	1	EXT1
0	-	0	Spare0	0	EXT0

Write output byte association table

#### 4.16 Set I/O

0xA0 0x10 <id> <MS ><MM><LS> 0x50

This command sets unused pins on the expansion connector to input or output. To allow space for future boards with more I/O the command has 3 bytes but the MS byte is currently unused. The following table shows which pins on the expansion connect are controller by which bit.

MS byte bit	Controls	MM byte bit	Controls	LS byte bit	Controls
7	-	7	DAC1	7	EXT7
6	-	6	DAC0	6	EXT6
5	-	5	ADC3	5	EXT5
4	-	4	ADC2	4	EXT4
3	-	3	ADC1	3	EXT3
2	-	2	ADC0	2	EXT2
1	-	1	Spare1	1	EXT1
0	-	0	Spare0	0	EXT0

Set I/O byte association table

Setting a bit to 1 makes the pin an input. Setting a bit to 0 makes the pin an output.

The command has no effect on pins which are assigned a function. Thus pins which are set as end-stop will remain operating as a digital input, pins which are set as ADC will remain operating as analog input,

and pins set as DAC will remain operating as analog output. In effect, to use a pin for input or output you must *first* disable its special operating mode. That must be done with a separate command. The following table lists how to make the pins available for input/output mode.

Pin	How to reclaim for user access
EXT0	Disable motor 0 end-stop A
EXT1	Disable motor 0 end-stop B
EXT2	Disable motor 1 end-stop A or use motors 0/1 as stepper
EXT3	Disable motor 1 end-stop B or use motors 0/1 as stepper
EXT4	Disable motor 2 end-stop A
EXT5	Disable motor 2 end-stop B
EXT6	Disable motor 3 end-stop A or use motors 2/3 as stepper
EXT7	Disable motor 3 end-stop B or use motors 2/3 as stepper
ADC0	Disable ADC0 channel
ADC1	Disable ADC1 channel
ADC2	Disable ADC2 channel
ADC3	Disable ADC3 channel
DAC0	Disable DAC0 channel
DAC1	Disable DAC1 channel
HALT	<i>Cannot be reclaimed</i>

Expansion connector pin reclaim table

#### 4.17 Set ADC/DAC

```
0xA0 0x12 <id> > <ADC ><DAC> 0x50
```

This command enables or disables the on-board ADC and DAC channels. A reason to disable a channel is to use the pin on the expansion connector for user input or output.

The LS 4 bits of the ADC byte enable or disable an ADC channel. Bit 0 enables/disables ADC0, bit 1 enables/disables ADC1 etc. If the bit is set (high) the ADC channel is enabled. If the bit is clear the ADC channel is disabled.

The LS 2 bits of the DAC byte enable or disable a DAC channel. Bit 0 enables/disables DAC0, bit 1 enables/disables DAC1. If the bit is set (high) the DAC channel is enabled. If the bit is clear the DAC channel is disabled.

All unused bits are reserved for more ADC/DAC channels in the future.

#### 4.18 Board configure

```
0xA0 0x?? <id> <MS ><MM><LS> 0x50
```

This commands configures a board for various operating modes. Currently there are three board features which can be set:

- Synchronous mode
- Attention signal mode
- Channel error mode

##### 4.18.1 Board Synchronous command mode.

If bit 0 of the LS byte is set the board works in synchronous command mode. For details about the synchronous mode see § 5.4.2 *Synchronous* .

#### 4.18.2 'Attention' signal mode.

'Attention' is a signal shared between all boards which goes to the Raspberry-Pi. (Or the RTS line of the RS232). A controller can only pull the line *low*.

Code	Attention signal mode
000	Off (=High)
001	Low as long as a stepper motor is running
others	<reserved for future use>

As the attention line is shared between all motors it will only go high if nobody pulls it low. So for the mode 001 this means the line will go high if all stepper motors have stopped running. (That is: only for motors on those boards which have their attention line mode set to 001). The status of the stepper motors is checked every millisecond. Thus there may be a delay of up to 1 millisecond between the last stepper motor stopping and the attention line going low.

The attention signal operating mode is placed in bits 1-3 of the LS byte.

For the attention line to work correctly, you must first set the mode, *then* start the stepper motors. If you set the mode to 1 and the stepper motors are already running the line is not updated.

#### 4.18.3 Stop on error.

Each motor controller has 2 error signals. When an error is detected the channel is disabled to prevent damaging the output. The error signal is also passed to the microcontroller which can respond to it. For more details see § 6 *Motor error*.

The user can program the following responses:

- Ignore error: The controller takes no further action.
- Stop channel: Stop the channel with the error.  
(This is not available for stepper motors)
- Stop channel pair: Stop both channels of the motor controller.
- Stop board: Stop all motor controllers of the board (four channels).
- Stop system: Stop all motors on all boards.

Code	Error handling
000	No error propagation
001	Individual channels A,B,C,D
010	Paired channels A&B (C&D)
011	Whole board (A-D)
100	Whole system (A-D on all boards)
101	<Unused>
110	<Unused>
111	<Unused>

The error handling bits are placed in bits 4-7 of the LS byte and the MM byte.

#### 4.18.4 Board configure command overview.

The table below shows where all the board configure bits reside in the three bytes.

MS byte bit	Controls	MM byte bit	Controls	LS byte bit	Controls
7	-	7	Error chan. D bit 2	7	Error chan. B bit 0
6	-	6	Error chan. D bit 1	6	Error chan. A bit 2
5	-	5	Error chan. D bit 0	5	Error chan. A bit 1
4	-	4	Error chan. C bit 2	4	Error chan. A bit 0
3	-	3	Error chan. C bit 1	3	Attention mode bit 2
2	-	2	Error chan. C bit 0	2	Attention mode bit 1
1	-	1	Error chan. B bit 2	1	Attention mode bit 0
0	-	0	Error chan. B bit 1	0	Sync mode

Board configure command table

The MS byte of this command is currently unused.

#### 4.19 Read board status

0xA0 0x03 <id> <MS ><MM><LS> 0x50 0x50 0x50 0x50 0x50

This commands returns some status information of the board. The following table shows what the return status bits represent.

MS byte bit	Value	MM byte bit	Value	LS byte bit	Value
7	0	7	0	7	ES7
6	0	6	0	6	ES6
5	0	5	ATTn	5	ES5
4	0	4	HALT	4	ES4
3	0	3	ENB_D	3	ES3
2	0	2	ENB_C	2	ES2
1	0	1	ENB_B	1	ES1
0	0	0	ENB_A	0	ES0

System status byte association table

This command will return 5 bytes:

The first byte is the original id.

The second byte is 0x03

Bytes three, four and five are the MS,MM & LS values read.

The status bits are such that a *high* bit indicates a special or error condition.

The ES0-ES7 lines indicate the end-stop active values. If high the end-stop is activated (and hopefully the motor has been stopped). On the board an end-stop signal can be active high or active low. The micro controller takes that into account when producing the board status bits and corrects the polarity. Thus a high status bits always means an active end-stop.

The ENB\_A..ENB\_D status bits are the status of the motors controller error lines. High (1) means an error. You are unlikely to see these lines active when the current is too high as the controller is immediately switched off This means that if you read one of these lines as high there is a high probability that the chip is too hot. <TO DO: latch A-D error status bits>

Low (0) means no error. (Note that the ENB\_AB and ENB\_CD line themselves are active low). For details see chapter **6 Motor error**.

The HALTED bit is high if the HALTn line is active and the system is in the halted state. (Note that the Halt line itself is active low).

The ATTN status bit reflects the actual status of the ATTN line.

*As the command returns 5 bytes it must be followed by at least 5 bytes of 0x50.*

## 4.20 Clear errors??

## 4.21 Read motor status

0xA0 0x14 <id> 0x50...0x50

This commands returns some status information of a motor.

This command will return 16 bytes:

The first byte is the original id.  
 The second byte is 0x03  
 Bytes 2..16 have the motor status packed in them. .

The following table shows what the return status bits represent.

0x14

*Todo: returns the motor status and remaining steps.*

*Has been done need documenting: returns 16 bytes. The first two are the usual: command, id*

*This C-code extracts the information:*

```

status->mode           =rec[2] & 0x0F;
status->ramp           =(rec[2] & 0xF0)>>4;
status->endstop        =rec[3] & 0x3;
status->endstop_polarity=(rec[3] & 0xC)>>2;
status->move           =(rec[3] & 0xF0)>>4;
status->frequency      =(rec[4]<<16) + (rec[5]<<8)+rec[6];
status->duty_cycle     =(rec[7]<<8)+rec[8];
status->steps          =(rec[9]<<16) + (rec[10]<<8)+rec[11];
status->remainder     =(rec[12]<<16) + (rec[13]<<8)+rec[14];


```

## 5 Operating details

### 5.1 End-stops

Often a motor is controlling a mechanical part which is limited in its movement. In that case the motor should not move the mechanical part beyond a certain limit. Therefore there are switches (mechanical or optical) which tell the motor to stop moving in that direction. This is what is called an end-stop in this manual.

It is not possible in this manual to talk about the 'direction' of a motor. The direction depends on how the user connects the motor wires. By reversing the wires the 'direction' changes. Therefore I use the nomenclature A and B. When a motor is moving in direction 'A' it is stopped if end-stop condition 'A' is seen. The other end-stop (B) has no effect on the motor when it is moving in direction 'A'.



Each motor has been assigned two input pins which can be programmed as end-stops. If an end-stop is active the motor cannot be started to move further into the end-stop direction. If an end-stop becomes active and the motor is moving into its direction, the motor is stopped.

End-stops can be enabled, disabled and can be programmed as active high or active low.

The following table shows the relation between the motors, the end-stops, the inputs associated and the travel direction it guards.

Motor	End-stop	Pin	Brushed direction	Stepping Direction
0	A	Ext0	1 (binary 01)	Positive
0	B	Ext1	2 (binary 10)	Negative
1	A	Ext2	1 (binary 01)	-
1	B	Ext3	2 (binary 10)	-
2	A	Ext4	1 (binary 01)	Positive
2	B	Ext5	2 (binary 10)	Negative
3	A	Ext6	1 (binary 01)	-
3	B	Ext7	2 (binary 10)	-

End-stop association table.

The end-stop system works only if the user has set the motor direction correctly. The Gertbot associates a motor travel direction with an end-stop. Travel direction A means to motor is expected in due time to active end-stop A. If you find the motion is in the opposite direction there are two ways remedy this:

1. You can swap the wires of the two end-stops A and B around.
2. You can invert to motor rotation direction.

You can change the direction of a brushed motor by swapping the two wires. You can change the direction of a stepper motor by changing multiple wires. See the operating manual of your stepper motor.

### End-stop polarity

The end-stop inputs have a pull-up resistor. Thus if an end-stop is not connected it will read as high (1). From that it seems most convenient to use active-low end-stops. *However it is better to use active high end-stops.*

If possible you should always use active high end-stops. The reason is that if for some reason the wire between your end-stop switch and the board brakes, the end-stop will become high and thus indicate a stop. With an active low end-stop the motor will hit the switch which is no longer connected and keep traveling!

For more protection you can add a second switch after each electronic stop which is in series with the motor power. If the first switch fails the second one will cut off the power to your motor. But you then have to manually rotate the motor shaft to free the switch again.

If you don't need end-stops you can disable the function and use the pins as a general purpose I/O.

## 5.2 Halt

There is a common 'halt' line. If that is pulled low every CPU will remove the power from all motors and all activity will stop. The 'halt' line is common between all cascaded motor boards. The 'halt' line can be pulled low by the user or by the system itself. You are only allowed to pull this signal low (connect to ground). Note that you can not start any motor when the halt line is low.

The HALT input can be used to implement the 'big red emergency' button:



## 5.3 Frequency settings

The stepper motor frequency and the PWM frequency are programmable. Especially for the stepper motors it is important that you never get a pulse which is shorter than what the motor can respond to. If that happens the actual position of the motor will no longer corresponds to what the computer thinks it is. Special attention has been given to the code which sets the frequency so that a step pulse may be slightly longer then the programmed period, but it never is shorter. There is one exception to this rule: on an emergency HALT all power is removed from all motor simultaneously. This will cut short any step pulses in progress.

### 5.3.1 Jitter.

The PWM of the brushed motors is completely done by hardware timers. Thus they are very accurate. However the stepper motors are controlled by the CPU using interrupts. This means there is the probability that the pulse width will be slightly longer. This will happen if the stepper-timer interrupt goes of and at the same time the CPU is busy with a different interrupt routine or is running a critical section. Measurements have show the jitter to be smaller than 5 $\mu$  seconds.

### 5.3.2 Accuracy.

The stepper motor frequency has been given a very wide range. This is so some applications can run their stepper motors at 5KHz. Whilst others, e.g. who want to debug, want to run them at 0.25 Hz (1 step every 4 seconds). Therefore the step frequency is made a 24 bit parameter. The smallest possible step frequency is 1/16 Hz (One step every 16 seconds). The maximum is 5 KHz (5000 steps/sec). The frequency is implemented in three ranges and in each range the accuracy is better then 0.2%.

[ the step frequency is send as a 16.8 integer. That is: you send a 24 bit number. The MS 16 bits are the integer part, the LS 8 bits are the fractional part. In practice this means that you multiply your frequency by 256 before you send it out. Thus a frequency of 5KHz is send as  $5000*256=1280000$  (0x138800). 1/16 Hz is passed as  $0.625*256=16$  (0x000010). ]

The stepper frequency is better then 0.02% accurate. Also the stepper motors frequencies are all derived from the same master source clock but further work independent. This means that you can use the stepper frequencies to replace the Bresenham line drawing algorithm.

#### The math.

The CPU runs of a 64MHz clock. The PWM is generated by a timer which has a 16-bit counter and a number of pre-dividers.

I started with the (arbitrary) target of a minimum step frequency of ¼ Hz (4 seconds per step) and a maximum frequency of 4 KHz. That is a range of 16000. At first glance a 16-bit parameter can easily cover that range. Alas! The problem lies in the steps you can take. If we start with a frequency of 16KHz we get as minimum frequency  $16000/65535 = 0.24$  Hz which was our target. However at the top frequencies we get:  $16000/4 = 4000$ . (Yes our maximum frequency. ). But the next one down is 3200Hz. Which is a step of 800Hz., 25%. That is obvious unacceptable. Therefore the method had to use a variable pre-divider followed by the 16-bit counter.

To get frequencies in steps of at least 1% we can divide maximum by 100. Now I went around the loop of all the possibilities and found that with little effort we can get a bit more out of the system. Minimum frequency 1/16 Hz.

As the highest resolution is at the lowest frequencies the sweet spot is 7.6Hz and 488 Hz. So a frequency above 7.6 Hz is derived from the 500KHz clock and everything below of the 3906 Hz clock. This also gives that the smallest divider is 500 and thus for all frequencies the frequency step is better then 0.02%.

Pre-Divider	Master Freq.	Min Freq.	max Freq 0.02% accurate
16384	3906.25Hz	1/16 Hz	39
128	500KHz	7.6Hz	1000
2	32MHz	488.3Hz	5000

Just as information snippet: The stepper motors are all controlled in software running from a timer interrupt. Bench marks have shown a maximum stepper frequency of ~500KHz if we run one motor and the CPU has *nothing else to do*. Obviously we want to stay far away from that so I decided to go for a maximum frequency of 5KHz.

## 5.4 Synchronous operation

Especially with four boards and 16 motors it can take some time to send commands to all motors. Therefore the Gertbot has two ways of starting motors in almost perfect synchronisation.

### 5.4.1 Direct commands.

Direct commands are specifically added to support systems which produce individual "step" commands. Each command can make a stepper motor take between 1-7 steps in either direction. Currently there are two commands:

1. 0xA1 <start board 0>
2. 0xA4 <start board 0> <start board 1> <start board 2> <start board 3>

Direct commands are special in that they do NOT need a leading 0xA0 or a trailing 0x50!

The <start board x>command bytes are interpreted different for brushed and stepper motors.

This is the command byte interpretation for brushed motors:

Byte		Action
MS	LS	
xxxxxx	00	Motor 0 stop
xxxxxx	01	Motor 0 run direction A
xxxxxx	10	Motor 0 run direction B
xxxxxx	11	Motor 0 no change
xxxx	00xx	Motor 1 stop
xxxx	01xx	Motor 1 run direction A
xxxx	10xx	Motor 1 run direction B
xxxx	11xx	Motor 1 no change
xx	00xxxx	Motor 2 stop
xx	01xxxx	Motor 2 run direction A
xx	10xxxx	Motor 2 run direction B
xx	11xxxx	Motor 2 no change
00	xxxxxx	Motor 3 stop
01	xxxxxx	Motor 3 run direction A
10	xxxxxx	Motor 3 run direction B
11	xxxxxx	Motor 3 no change

Below is the command byte interpretation for stepper motors. You can stop a motor, keep it unchanged or take between 1 and 7 steps in each direction

Byte		Action
MS	LS	
xxxx	0000	Motor 0/1 stop
xxxx	0001	Motor 0/1 no change
xxxx	SSS0	Motor 0/1 SSS steps direction A (SSS = 1..7)
xxxx	SSS1	Motor 0/1 SSS steps direction B (SSS = 1..7)
0000	xxxx	Motor 2/3 stop
0001	xxxx	Motor 2/3 no change
SSS0	xxxx	Motor 2/3 SSS steps direction A (SSS = 1..7)
SSS1	xxxx	Motor 2/3 SSS steps direction B (SSS = 1..7)

If you have a mixture of brushed and stepper motors connected to one board you can mix the commands bits of these two tables.

The baud rate is set to 57600 baud and it requires 20 baud clock cycles to transfer a direct command. This means you send single step commands at maximum 2880 Hz to one board.

#### 5.4.2 Synchronous commands

*Currently only the motor start & stop commands can be set synchronous.*

The synchronous mode is enabled or disabled using the board setup command (See § 4.18 Board configure) In synchronous mode the execution of the two start/stop motor commands


- Start Brushed Motor (0xA0 0x06 <id> <mode> 0x50)
- Take steps (0xA0 0x08 <id> <MS><MM><LS> 0x50)

is postponed until a "sync" command arrives. Thus you can send 'take steps' command to all stepper motors and then start them virtually at the same time using the 'sync' command. If you send multiple commands to the same motor, before the 'sync' is sent, only the last command is executed. All previous commands are lost.

There are some details to keep in mind:

- There will still be a small delay of max 4 micro seconds between the starting of the motors.
- The stepper motor **timer** is started on the sync command. The actual step will only take place after the stepper period has finished.

The diagram below shows what this implies:



## 6 Motor error

Each motor controller has two error outputs, one for each H-bridge. This output is pulled low by the motor controller itself when an error is detected. Possible causes for an error are:

- Current too high
- Temperature too high

An error condition *always* switches the motor controller channel *off*. This safety measure can not be disabled. It reduced the risk of the controller getting damaged.

### 6.1 Reaction to an error

The motor error signals are connected to the processor. The user can program the controller to take various action if an error is seen:

- The error signal is ignored.
- The motor channel is switched off.
- The pair of channels is switched off.
- All four channels on the board are switched off.
- All channels on all boards are switched off.

#### A: Ignore error

This means the processor ignores the incoming error signal. Even if the processor ignores the error signal, the motor channels (H-bridge) will still be switched off. This can lead to oscillations. For details see 6.2 *Oscillation*. It is not recommended to run in this mode, as your motor controller will be running at the extreme of its operation current and in due time may be damaged.

#### B: Switch channel off

In this mode the processor switches the motor channel off. It also posts an error message telling the user which channel saw an error. To start the motor again you must re-send a motor start command (or a step command). See § 7 *Appendix A: error codes*. about error messages.

### C: Switch pair of channels off

In this mode the processor switches the motor channel pair off. Thus an error on channel A (or C) will also stop channel B (or D). This is most convenient for stepper motors. It also posts an error message telling the user which channel saw an error. To start the motor again you must re-send a motor start command (or a step command).

At the moment the controller will NOT automatically be into this mode if you enable the channels in stepper -motor mode. This is still open as a future enhancement. It is up to the user to set the error code for *both* channels into 'paired' mode.

### D: Switch board off

In this mode the processor switches all four channels of the board off. It also posts an error message telling the user which channel saw an error. See the section about error messages. To start the motors again you must re-send a motor start command (or a step command).

### E: Switch all motor controllers off

In this mode the processor switches all four channels of the board off. But next it asserts the HALT line. This will cause the whole system to halt: All motors will switch off. It also posts an error message telling the user which channel saw an error. All other boards will additionally post error messages telling the user that the halt line was activated. The user must re-enable all motors by sending a start command to each.

## 6.2 Oscillation.

If the error is "current too high" and you have set the processor to ignore that error, we get oscillating. What happens is the following:

1. When a high current is detected the controller channel is switched off.
2. This causes the current to become zero.
3. As there is no current any more, the controller channel is enabled again
4. This causes a high current to appear again and we are back at step 1.

Due to the fast switching on and off of the current some motors may produce an audio signal, a 'crackling' sound.

With stepper motors this can cause the motor to take steps and the integrity of the system is lost.

Oscillating can also happen if the error is "temperature too high". But the oscillations will be significantly slower as it takes many seconds for a device to cool down and then heat up again.

## 6.3 Soft start / Inrush current

Brushed motors often draw a lot of current when they start-up. This is called the inrush current. The high inrush current is likely to trip the over-current detection and stop the motor again. To prevent this from happening the Gertbot system provides a soft start mode. In this mode the signal duty-cycle starts at zero and is slowly increased till the value the user has selected. There are 16 soft start values which give a range of start-up times.

Time (sec)	Code						
Off	0x0	0.375	0x4	2.5	0x8	2.5	0xC

0.05	0x1	0.5	0x5	1.5	0x9	3	0xD
0.125	0x2	0.75	0x6	1.75	0xA	4	0xE
0.25	0x3	1	0x7	2	0xB	5	0xF

Soft start time in seconds.

The value gives the time it takes for the duty-cycle to get to 100%. If the user has set the duty cycle lower the soft start will take proportionally shorter.

Even if you brushed motor does not require soft-start to begin running, you may find that you need it to prevent extreme currents when you try to reverse the motor direction without stopping.

**Beware:**

The soft start sequence is only enabled when you send a motor start command. **It is not activated on each cycle of the PWM.** Thus if you set a PWM frequency of 10 Hz a DC brushed motor is started 10 times per second. You will get an inrush current ten times a second. That is likely to trip the over current protection.

Using a very low duty-cycle frequency with DC motors will cause excessive currents to flow and thus the controller can become hot.

## 7 Appendix A: error codes.

Code	Error condition
0x0000	There are no errors to report.
0x0001	Serial input queue overflow: The serial data was coming in faster than the CPU could process. One or more input bytes have been lost.
0x0002	Internal system error. System got into a state which should not be possible. This error should appear during SW development only!
0x0003	Mode command value error You specified a non existing mode.
0x0004	End-stop parameter wrong. Only values 0-15 are allowed
0x0005	DC motor frequency error: Motor was not in DC mode. You tried to set a brushed frequency on a motor which was off or was specified as a stepper motor.
0x0006	Duty cycle error: Motor was not in DC mode. You tried to set a duty cycle frequency on a motor which was off or was specified as a stepper motor.
0x0007	Illegal frequency given in set-brushed-frequency command The frequency you specified was out of range 10Hz-30KHz
0x0008	Illegal duty cycle given in set-brushed-duty-cycle command The duty cycle you specified was out of range 0-1023
0x0009	Stepper motor command given to none-step channel. You gave a 'step' command to a motor which was off or in brushed mode
0x000A	Illegal frequency given in set-stepper-frequency command (0x09) The frequency you specified was out of range 1/16-5000
0x000B	
0x000C	
0x000D	
0x000E	Start command given with halt active. You tried to start a motor but the halt line is active
0x000F	Attempt to set too many timer events. The program attempted to schedule a timer event but there were none left. (This error should appear during SW development only!)
0x0010	Serial output queue overflow. The board tried to send a response but the output queue was full. Data has been lost. This can only happen if you did not send enough end-of-message bytes
0x0011	
0x0012	Write to DAC which is disabled.
0x0013	Read from ADC which is disabled
0x0014	Enable ADC illegal mask bits. Only bits 0-3 may be set
0x0015	Enable DAC illegal mask bits. Only bits 0,1 may be set

## 8 Appendix B: Technology.

So you want to start playing with motors but you have no idea where to start. To begin with: I can't teach you all there is to know about this subject. First because I don't have the time, second because I don't know it all either even after forty five years in electronics. Fortunately the internet is a wonderful source of information, at least on the technical level where most of the information seems to be true. So read up, use search engines, use Wikipedia. What follows is just a short brief explanation of terms you might want to get familiar with

### 8.1 DC voltage.

A Direct-Current power source which gives out a constant voltage and current. It is often show using this symbol:



Batteries are such a source as well as most 'power bricks' which you plug between the power socket in your house and some equipment:



It seems that a DC voltage below 60V is deemed to be safe but I suggest for these motors you do NOT use anything above 18V unless you know a lot about electronics and electricity and are certain about what you are doing (Which is probably NOT the case otherwise you would have skipped this section) . Why? Read the next sections.

### 8.2 AC voltage.

The opposite of a DC power source is an AC (Alternate Current) which is what comes out of your home socket. AC power sources are much more dangerous than DC. An AC source below 25 volt RMS (35 V peak-peak is deemed to be safe. Anything above is dangerous).


**Well you are using a DC power source of 30V so you are safe not?**

**NOT!**


The board will take your DC power source and turn it into an AC voltage. The output of the motor controllers in stepper mode is an AC signal. The peak-peak voltage is twice the DC voltage on the input. To see how this is possible look at the section which describes the H-bridges. Thus the 30 volts of DC you put into your motor controller will come out as 60V peak-peak AC on the stepper motor pins. Dangerous!

### 8.3 H-bridge.

Below is a picture of an H-bridge. It consists of four switches with a middle tap. The shape of which is sort of like an H:




In reality the switches are made using transistors or FETs but for the explanation how it works switches are easiest to understand. The switches are connected to power and ground connections. So at the left we add the symbol for a battery and the complete electrical diagram becomes:




The two contacts in the middle A and B can be connected up to a DC motor.

If we close switch S1 and S3 we get that current is flowing from the + to the - following the red path in the picture below.




We see that the current is flowing through the motor from A to B. This will cause the motor to rotate.

If we close switch S2 and S4 we get that current is flowing from the + to the - following the red path in the picture below.



We see that the current is again flowing through the motor, but from B to A just the opposite direction than in the previous picture. Thus the motor will also rotate in the opposite direction.

Here are some more possibilities:



These are what is called 'braking' scenarios. The motor is shorted which means any residual current in there can flow and will cause the motor to brake. The Gertbot does not support these two modes.


There are two more possibilities but those are never used: If S1 and S2 are closed or if S4 and S3 are closed. In that case the switches form a short circuit from + to - and unless precautions are taken something will get damaged.

**Note that the original DC voltage of the battery is now changed into an AC voltage on the motor contacts A and B which is twice as high. As AC voltages are a lot more dangerous than DC you should not use voltages above 18V.**

#### 8.4 DC Brushed motor.

DC motor, brushed motor or DC brushed motor are all names of a motor which runs of a DC voltage. The more voltage you apply the faster it runs. The force it can apply also goes up with the voltage. Unfortunately this means the running a DC motor slowly and still providing a lot of force is not possible.

A DC motor has a single coil:




You can reverse the direction of rotation by reversing the voltage over the wires or by swapping the wires around (which is the same).


## 8.5 Stepper motor.

### 8.5.1 Connections

Most stepper motor come with four or six wires. The following is a diagram of a stepper motor with six wires:




To generate a magnetic field you have to send a current through one of the coils. There are several ways of doing this. Here we connect the middle of a coil to the + and then we can use two switches to enable either one or the other coil.




The blue arrow indicate the direction of the magnetic field. As you can see the two operating modes have opposite magnetic fields. I have not drawn it, but you can imagine that the same is possible with the coil at the bottom. The advantage of this method is that you need only two switches to flip the magnetic field of the coil around. But the disadvantage is that you use only half of each coil. For two sets of coils you need four switches.

In the following diagram we drive the coils from their extreme connections. The middle tap of the coil is not connected to anything. Again we get two opposite magnetic fields but in this case the full coil is active so the magnetic field we can generate is twice as strong. But to drive the connections from **A+**, **B-**

to the inverse: **A-**, **B+** you need more than two switches. If you have read the previous paragraphs it will be obvious that this can be achieved with an H-bridge. For two sets of coils you need two H-bridges.




A stepper motor with four wires is not much different from one with six wires. The middle taps of the coils are missing:



### 8.5.2 Mechanics

Most stepper motors have a permanent magnet with 'teeth' which is mounted on the axis. The following are a set of diagrams which try to explain the *principle of operation*. The current in the external coils is changed such that the rotor is moving from one position to the next.



In reality the internal of the motor is much more refined, with many small teeth and two sets of teeth on the rotor. The two sets of teeth are slightly offset and the magnetics are controlled in such a way that the rotor switches from one set of teeth to the other.

### 8.5.3 Rotor hold.

From the pictures in the diagram above you can see that the rotor will be held in place if the magnets are active. However if the power is removed from the magnets the rotor can freely turn. This means a stepper motor that is halted (not running) can be stopped in two different states:

- Stopped with magnets off.  
In that case a small external force can change the position of the rotor.
- Stopped with magnets on.  
In that case the rotor will stay in position and it will take great force to move it out of position.



## 8.6 Inductors.

The windings of your brushed motor or your stepper motor are inductors. You should know a bit about inductors if you want to work with motors.

### 8.6.1 Switching it on.

First rule of inductors: They don't like a change in current!

So they will 'fight' any increase in current. The following might sound strange but: as soon as you put a voltage on the coil there will be at the beginning no current! No current means no magnetic field and thus your motor will not make any movement. After a while (a few microseconds to milliseconds) the current will start flowing and slowly the magnetic field will increase and the rotor starts moving. The following is a diagram plus graph, showing what happens if you apply a voltage to a coil:



At time  $t=0$  we close the switch. The current starts to rise and after a while it gets to its maximum value. The time that takes depends on the motor coil. In a small coil it can happen in a few microseconds, a large coil can take several milliseconds to reach the maximum current.

In the diagram you will notice a resistor next to the inductor. That resistor represents the internal resistance of the inductor. The resistance is important as it determines the final current value which will flow. A good inductor will have a very low resistance.

Beware that this effect is totally different from the in-rush current. The in-rush current is caused by a lack of counter-magnetic field when the rotor is not yet spinning. The in-rush current also happens on a different time scale: in tens of seconds to seconds, not the micro- and milliseconds mentioned above.

### **8.6.2 Switching it off.**

First rule of inductors: They don't like a change in current!

This also means that if there is already a current flowing and you try to stop that the inductor will fight that as well. One way to fight the current is that the inductor will 'push back' by generating a counter-voltage. This is where inductors can get very, very nasty. If you switch the current off, the 'push back' voltage of the inductor can become thousands of volts high<sup>4</sup>. First it can give you a nasty shock (literally!). Second it can blow up your circuit. To prevent this the motor controllers have built-in protection diodes.

---

<sup>4</sup> That is how the ignition spark in your petrol engine is generated!

## 9 Appendix C: asc2bin

asc2bin is utility which takes ASCII text and converts it to binary format. These binary files can then be send to the control port on the Raspberry-Pi (cat start01.bin >/dev/ttyAMA0). It is specially written for the Gertbot to help you generate simple command files. This is the usage text:

```
Usage: asc2bin <inputfile> [outputfile]
asc2bin takes an ASCII file and converts it to binary format
The first argument is the name of the input (text) file.
An optional second file name is used to write the data to.
If there is no second file name the input filename
appended with '.bin' is used as output file.
If the output file name is '-' the binary data is send to stdout.
e.g. you can use 'asc2bin example.txt - | /dev/ttyAMA0'
Input file format:
  All text after a '/' or '#' is ignored.
  Lines must only contain Hex characters or spaces.
  (Except for the unavoidable end-of-line characters.)
  Hex characters are 0-9, A-F, a-f.
  Lines must hold an even number of ASCII hex characters.
  Lines may be maximum 1024 characters long.
The program has the following return values:
  0: success.
  1: File open failure.
  2: Input file format error.
  3: Fatal system error.
```


Here is an (untested!!) example input file

```
#
# Demo file to drive Gertbot from ASCII text file.
#
# Start with some end-of-command bytes, can't hurt
50505050505050
# Set motors 0 & 1 on first board to brushed mode
A001000150
A001010150
# Set frequency of both to 1KHz
A0040003E850
A0040103E850
# Set motor 1 to 75% duty cycle
A00501030050 # 0.75*1024=0x300
# Start 0 and 1 with a 0.75 second ramp time
A0 0x06 0x00 0x62 50
A0 0x06 0x01 0x62 50
```

I'll leave as an exercise for the reader to come up with a better version. e.g. A version that recognises decimal and hexadecimal numbers, splits large number into multiple bytes and any other useful and useless features you can think off.

## 10 Appendix D: software

The Gertbot archive contains various deliverables. Some of these are complete programs (gertbot), others are only source code files with example code (example\_driver). This is an overview:



The beginnings of software in python is available as well.