



Electrical Test Tools > Electrical Testers >

## Fluke 9040 Phase Rotation Indicator



- 3 phase indication
- Indication of phase
- Clear LCD display
- No battery required



[Electrical Test Tools](#) > [Electrical Testers](#) >

## Fluke 9040 Phase Rotation Indicator

Technical Specifications	
Voltage range	40-700 V
Frequency range	15-400 Hz
Operating timer	Continuous

Environmental Specifications	
Operating temperature	0 °C to 40 °C
Dust/water resistance	IP 40

Safety Specifications	
Electrical Safety	EN 61010, EN 61557-7
Overvoltage category	CAT III, 600 V

Mechanical & General Specifications	
Size	124 x 61 x 27 mm
Weight	200 g
Power supply	From unit under test
Warranty	2 years